

OPTION 3014

AUTO ZERO

- Used to zero the display.
- Can be activated by pressing the * key.
- Can be activated by digital input signal. Potential free.

- THE OUTPUT WILL FOLLOW THE DISPLAY ZERO.



P O Box 418, Honeydew 2040 South Africa
21 Precision Street, Kyaland Randburg.
Telephone: +27 11 462-1920
Telefax: +27 11 462-1958
email: info@instrotech.co.za
web: www.instrotech.co.za

